



Church Walk is a tree lined picturesque gated road with former estate dwellings fronting its northern side and the parish church sited on the south side



The former estate dwellings originally had their own outhouses for washing and storage. They are important features which should be retained.



Although Rose Cottage on Church Walk has a steep pitched roof, the dwelling is generally out of character with the rest of properties on the walk by way its rendering, use of UPVC windows and design. Any new dwellings built in Shackerstone should respect the traditional character of the settlement.



61 Church Walk is a fine example of a Gopsall Estate workers property, the traditional character of which has been spoilt due to its inappropriate bays and windows



The two estate properties 59 & 60 Church Walk have retained most of their original features including hood mouldings, steep roofs and full height casements



57 Church Walk built in the Arts & Crafts style. Unfortunately, the white painted door and dormers are too visually prominent and the window openings appear to have been modified without retention of any of its original detailing.



49 Church Walk has its original detailing over its windows.



Unfortunately, with its original window being replaced by a larger window the original detailing on 50 Church Walk has been lost.  
This has unbalanced the unity of the two properties