

## CONGERSTONE CONSERVATION AREA MANAGEMENT PLAN

## PHOTOGRAPHS OF DETAILED PROPOSALS



(1) Existing fence at the entrance to the conservation area on Shackerstone Road is an incongruous feature which needs replacing with a more traditional fence



(2) Modern brick wall on Shackerstone Road is out of character with the boundary hedges generally running along the residential frontages



(3) The block wall on Shackerstone Road needs replacing with traditional Carlton stone wall



(4) Existing hedge needs extending to replace unattractive timber fence at the Church Field



(5) Existing fir tree hedge is out of character and scale at the Parish Field restricting views to the Parish Church



(6) Redundant concrete fence posts need removing from the Parish Field



(7) Low level timber fence and fir trees are incongruous features on Barton Road which need replacing with more traditional materials



(8) Area would be improved on Barton Road if the unsightly concrete apron was replace with granite setts to match the adjacent property