




(9) The former village pub with eyebrow windows on Barton Road is to be restored



(10) Existing hedgerow on Barton Road needs replacing with Carlton Stone wall



(11) Rear extension to the church hall is out of character with the main building



(12) The existing traditional Carlton stone walls, many of which are in poor repair, are important features in the conservation area which should be retained at all cost



(13) Modern brick wall is an incongruent feature at the junction of Main Street and Shadows Lane. Its replacement with a Carlton Stone Wall would visually improve the junction setting



(14) The carriageway on Shadows Lane needs defining and the parking area re-surfaced in a traditional material



(15) Gaps in hedgerow need to be re-planted along boundary of new housing development on Shadows Lane



(16) Timber fence on Main Street needs replacing with Carlton stone wall to link up to adjoining walls