

The unity of the boundary walls fronting this pleasant terrace has been lost. The wall at 4 Mill Street needs to be rebuilt in blue brick and consideration should be given to tying all the front walls together utilising a common coping. The chimney stacks on a couple of properties needs replacing. A considerable number of garden walls in the conservation area tend to be constructed with blue brick

The shop front to this property

requires improving

as tet 156 High Street is in a prominent location in the conservation area and has been derelict for a considerable period of time. Consideration now needs to be given to serving a Section 215 Notice to ensure it is renovated within a reasonable period of time. The front boundary to the adjacent land the area behind re-surfaced The plastic cladding on this property is an unattractive feature and should be removed to reveal the original brickwork. The signs need to be rationalised and if possible the flue on the side of the property removed

Ivy needs to be removed from gate pier

The grass verge fronting Church Lane should be considered for tree planting

Provide a heritage street nameplate on the corner of Church Lane

The brick pier at 91 High Street and wall at 97 High Street need rebuilding

The stone plinth to the Red Lion pub needs to be re-laid

© Crown copyright. All rights reserved Hinckley & Bosworth Borough Council LA100018489 Published 2010.

-111/

 $\neg \land \land$ 

へ

SLEYDALF