


**BURBAGE CONSERVATION AREA
MANAGEMENT PLAN - ADOPTED
13 DECEMBER 2011**



Consideration should be given to replacing the 2 street nameplates with parish council heritage nameplates

This area would benefit with a comprehensive landscape scheme

Consideration should be given to replacing iron railings that were removed from the front wall of the listed Cedar Lawns during the war. The tops to the metal gate piers also need replacing

Clear ivy from pier and wall

Tree grille and kerbing needs relaying and tree stake removed

This attractive open space would be considerably improved with the installation of heritage street lighting

Sited within the Horsepool, this would be an excellent location for a heritage street light that would help light up in the evenings both the Horsepool and the adjacent carriage way

The timber fence at this important location is an incongruent feature. Consideration should be given to replacing it with a traditional brick wall

Remove redundant litter bin and post

Relay pavers, remove foliage around tree bases and clear debris

Clear ivy from pier and wall

Remove redundant light from church wall

Clear ivy and restore 2 chest tombs

Churchyard pier that has been hit by a vehicle and moved slightly of its base, needs resetting

Unightly growth needs removing alongside this building

This attractive area would be improved if its curtilage was to be kerbed with granite kerbs. The dying tree needs replacing

Clear ivy from pier and wall

Existing hedge is unsightly. Consideration should be given to a replanting scheme or building a traditional brick wall

The area around the war memorial would be visually improved if the concrete kerbing was to be replaced with granite kerbs

These 3 concrete bollards should be replaced with traditional metal bollards

This part of the Horsepool would be improved if the 2 existing street lights were replaced with heritage lights

The wire mesh fence running along the frontage to the Congregational Church is an unsightly feature and needs to be replaced with a traditional brick wall and railings