

HIGHAM ON THE HILL CONSERVATION AREA MANAGEMENT PLAN - ADOPTED 22 DECEMBER 2009

Encouragement should be given to the restoration of traditional walls and chimney plots

A restoration project is required to restore the Fisher family tomb with an information board provided of the family's links with the village

Continuous stone wall needs to be retained intact

Consideration needs to be given to re-surfacing the frontage to Pump Row

The gates to the Church lichgate need repairing

Consideration should be given to resurfacing this area

The Oddfellows Arms pub on Main Street which is currently closed, occupies a potential development site. The pub however, which is sited in a prominent location at the junction with Nuneaton Lane, should be retained although the outbuildings could be demolished

This part of Main Street would benefit if traditional built walls were to be re-instated fronting the road

Traditional landscaping treatments suggested

King George's Field
(Recreation Ground)

The garage at the entrance to the conservation area has an adverse impact in the street scene. Its visual impact could be reduced if the garage door was to be painted in a dark colour

Area fronting bungalow and the Old Post Office needs re-surfacing with traditional materials

Public footpath needs signing

Replace lamphoods with piers

Replace existing street light with heritage light

The shop front treatment needs re-designing using natural materials in a traditional manner

The roof to the outbuilding to Elms Farm needs replacing with a traditional roof

The wall fronting Elms Farm needs completing with traditional coping provided and the area behind re-surfaced, preferably with granite sets

The cobbled surface on Barr Lane is an excellent feature that needs to be retained. The tarmacadamm carriage way needs cutting back

Satellite dishes should be located to avoid being visible from public spaces

