




The communal garage site accessed off Mill Lane is a particularly unattractive development adjacent to the conservation area boundary



A brick wall fronting Post Office Lane would be more in keeping with the locality similar to wall fronting the pub's beer garden



The existing hedge on the playing field needs continuing up Post Office Lane to help screen the existing fence



The listed Parish Church of St Peter's





The modern bricks utilised on the boundary wall and new dwelling on riverside are unsympathetic in colour and texture



A view looking south along Riverside. The iron fences and gaps to frontages should be replaced with brick walls. The grass verge is also being eroded with cars using it for turning.





Looking back along Riverside towards the church showing gaps to the street frontage



The picnic area on Riverside is in need of maintenance. In the long term consideration should be given to the re-design of the area





The dwelling situated at the junction of Hunt Lane and Bridge Lane is an attractive feature



The property 2 Witherley Road is an attractive listed building fronting the A5 which would be visually improved if the existing timber fence was replaced with a brick wall built of a similar brick to the property