



Bridge 46 (Fairfield Bridge) North elevation)
A fine brick bridge which has retained the majority of its original stone copings. The bridge has been badly repaired in the past and work is now required to rectify this.



Bridge 47 South Elevation



Bridge 47 (Congerstone Bridge) North Elevation
This road bridge is in good condition



Bridge 48 South Elevation



Bridge 48 (Dakins Bridge) North Elevation
This road bridge is in fair condition, however,
the springing points of arch are in need of repair



Bridge 48 showing the damaged brickwork requiring attention



Bridge 49 (Terrace Bridge) North Elevation
This road bridge is in fair condition, however,
the springing points of arch are in need of repair



Bridge 49 South Elevation



Bridge 50 (Bates Bridge) North Elevation
This accommodation bridge is in good condition. Copings have been re-bedded.



Bridge 50 South Elevation
Repairs have been unsympathetically completed in none matching brickwork



Bridge 51 (Bates Wharf Bridge) North Elevation
The bridge which provides vehicular access along a public road to Shackerstone Station is generally in good condition. However, the parapet wall has been repaired in a non matching brick with concrete copings have been utilized.



Bridge 51 South Elevation



Bridge 52 (Turn Bridge) North Elevation

Turn Bridge is where the towpath changes from one side of the canal to the other. The bridge has been repaired at various times in the past and is in good condition. However, the parapet wall has been repaired in a non matching brick and concrete copings have been utilized.



Bridge 52 South Elevation



Bridge 53 (Town Bridge) North Elevation
This road bridge has been repaired at various times in the past and is currently in good condition



Bridge 53 South Elevation



Bridge 54 (Hill's Bridge) North Elevation
The Bridge is generally in good condition



Bridge 54 South Elevation
Vegetation should be removed and parapets repointed



Bridge 56 : (Timms Bridge) North Elevation
The bridge is generally in good condition



Bridge 56 South Elevation



Bridge 57 North Elevation
There is slight movement of the arch
away from the parapet walls



Bridge 57 South Elevation



Bridge 58 South Elevation
The bridge has previously been repaired
and is generally in good condition



Bridge 58 North Elevation