



This area on Main Street has lost its enclosure and would benefit with the timber fence replaced with a traditional wall or hedge.



View looking towards properties on The Square. The farmland in the foreground is one of a number of important open areas in the village that help retain its rural character.



The concrete retaining slabs fronting 2 & 3 Blacksmith Lane are a poor visual feature. Consideration should be given to replacing the slabs with a wall of traditional character.



Although the large tarmac area fronting 1 – 4 Main Street has been provided for parking purposes, unfortunately, the loss of part of the grass verge does have a detrimental impact on the conservation area.



The grass verge on Main Street is an attractive feature in the village which should not be enclosed.



Ambion Cottage, a rendered property with a rosemary tiled roof that has had its windows modernized.



Hall Farmhouse, an early 17th Century Grade 2* listed building that has had a Victorian Wing added. The sequoia tree in the front garden, although lopped, is still a fine specimen.



Rear of Hall Farmhouse showing stone corner dressings.



The dutch barn and out buildings at Hall Farm still reflect the agricultural character of Sutton Cheney.



The stables at Hall Farm built 1893