


Key:

- Conservation Area Boundary
- Key Local Buildings
- Weak Areas
- North Lights
- Granite Kerbs
- Jitty
- Views to be protected

N NOT TO SCALE



ARTHUR STREET FACTORIES

- A. Former framework knitters cottages
- B. Boot and shoe cottages
- C. Boot and shoe outworkers workshops
- D. Methodist Chapel
- E. Victorian shop front

KEY LOCAL BUILDINGS

- 1. Sperope Factory
- 2. Hall and Gears Factory Offices
- 3. H Grewcock Factory
- 4. Konfidence Works (Hodgkin & Powers)
- 5. H Garner & Co
- 6. George Ward Ltd
- 7. Harvey, Harvey & Co
- 8. Small Workshop
- 9. Amos Moore and Co
- 10. Moulds & Moore